

# How to use a 4 Bay Docking Station for HAV and SAFE-DISTANCE

**REACTEC**

INFORM : PROTECT : DEPLOY



## Sign out

1. Press and release the Docking station button.



2. Wait until a red LED flashes next to a HAVWEAR to indicate which HAVWEAR to sign out.



3. Place a valid ID card on top of the HAVWEAR until a beep sounds.



4. Remove the ID card and the HAVWEAR will display the first name initial and first three letters of the ID card owner's last name.



## Collect

5. Remove the HAVWEAR which is ready for use.



## Protect & Connect

6. Insert the HAVwear into the holder so only the strap is in contact with the wrist. Snugly fit the strap around the wrist (do not remove until returning to a Docking station).



7 & 8. Before using each tool, press & release the HAVwear button once before placing the HAVwear over a tool tag until a beep sounds, to "Connect" to the tool. The display will show the last 4 characters of the tool ID to confirm connection.



9. Return to docking station at end of shift.

## HAVWEAR user tips

### How to assemble and fasten the HAVwear to the wrist

A holder and strap are required to secure a HAVwear to the wrist.  
NOTE: The wrist strap is personal and should always be subject to appropriate occupational hygiene procedures regarding cleaning and replacement.

#### Incorrect strap routing and wearing

HAVwear device is exposed to the skin and worn loosely on the wrist.



#### Correct strap routing and wearing

HAVwear device is behind the strap and worn snugly on the wrist.



## When at a SAFE-DISTANCE, HAVwear screen display & alerts

**Latest tool used**  
Last 4 characters of tool model number

**Exposure points**  
HAV risk exposure points

**Exposure traffic lights**  
Circles in coloured bar indicates thresholds reached

**Operator alerts**  
Beeps and vibrates

**Operator initials**  
First name initial and first three characters of last name

Below action value	EAV exceeded	ELV exceeded
Split into 3 equal sections to indicate incremental exposure		
2 sec alert	5 sec alert	10 sec alert
		20 sec alert

### HSE guidance on exposure thresholds

- BAV** Try to remain within this threshold
- EAV** Take actions to reduce risk
- ELV** Do not exceed this threshold

## Switch off/on the HAVwear during non tool use

- Hold the HAVwear button for 5 seconds until the screen displays "OFF".
- Release and then press the HAVwear button again for 1 second to confirm.
- To switch a HAVwear back on simply connect with a tool before use.

## SAFE-DISTANCE display when colleagues close



HAVwear display when too near a colleague

⚡ The HAVwear should be re-charged fully before being put into storage where not mounted in a powered up docking station. It is also recommended to recharge the unit on a regular basis (monthly) with a 1 hour top up charge.