

How to use a 15 Bay Docking Station for HAV and SAFE-DISTANCE



1. Place an ID card against the orange swirl icon on the Docking station to sign out a HAVwear.



2. Unclip the HAVwear from the bay with the flashing LED light.



3. Insert HAVwear into the holder so that the strap is in contact with the wrist. Snugly fit the strap around the wrist (do not remove until returning to a Docking station).



4. Before using each tool, press & release the HAVwear button once and place the HAVwear over a tool tag until a beep sounds, to "Connect" to the tool. The display will show the last 4 characters of the tool ID to confirm connection.



5. To "connect" to a SAFE-ZONE press the button on the HAVwear once, place the HAVwear over the SAFE-ZONE tag until a beep sounds. The display will show "SAFE" to indicate social distance detection is switched off.



6. Return to docking station at end of shift.

How to assemble and fasten the HAVwear to the wrist

A holder and strap are required to secure a HAVwear to the wrist.
NOTE: The wrist strap is personal and should always be subject to appropriate occupational hygiene procedures regarding cleaning and replacement.

Incorrect strap routing and wearing

HAVwear device is exposed to the skin and worn loosely on the wrist.



Correct strap routing and wearing

HAVwear device is behind the strap and worn snugly on the wrist.



Switch off HAVWEAR during non tool use

Press & release the HAVwear button once before placing the HAVwear over the tool tag on your hard hat until a beep sounds. The first 3 characters of the tool ID will display "OFF" to confirm.

WARNING

When returning a HAVwear and placing it into a bay of a Docking Station DO NOT push down on the HAVwear screen.



Cleaning Equipment

It is recommended an Isopropanol or similar alcohol based cleaning agent with an alcohol content of at least 70% is used for cleaning. This should be applied with a cloth and with the docking station powered down. Use of chemicals not fitting this description may cause damage.



The HAVwear should be re-charged fully before being put into storage where not mounted in a powered up docking station. It is also recommended to recharge the unit on a regular basis (monthly) with a 1 hour top up charge.

When at a SAFE-DISTANCE, HAVwear screen display & alerts

Exposure points
HAV risk exposure points

Exposure traffic lights
Circles in coloured bar indicates thresholds reached

Latest tool used
Last 4 characters of tool model number

Operator initials
First name initial and first three characters of last name

Operator alerts: Beeps and vibrates	Below action value	EAV exceeded Split into 3 equal sections to indicate incremental exposure	ELV exceeded
	2 sec alert	5 sec alert	10 sec alert
		20 sec alert	

HSE guidance on exposure thresholds

- BAV** Try to remain within this threshold
- EAV** Take actions to reduce risk
- ELV** Do not exceed this threshold

SAFE-DISTANCE screen & alerts

When you're too close to a colleague wearing a Reactec product, you'll receive a short buzz and vibration alerts. The alerts will intensify with time. You will receive repeated alerts until the distance between you and your colleague increases.

SAFE-DISTANCE
TOO NEAR: Move away from nearby colleagues
SAFE: Tagged into a SAFE-ZONE. Proximity detection is OFF

Battery Level
Indicates battery level

Operator Initials
First Name initial & first 3 characters of Last Name